Plasma Cutting Tips

- 1. Clean, dry, oil-free air is important.
- 2. Stay at recommended air pressure (more air is not necessarily better!)
- **3.** Touch torch tip gently to workpiece.
- **4.** When initiating a cut, start on the end of material to be cut and ensure arc has completely penetrated metal before proceeding further.
- 5. When completing cut, pause at the end to assure severance.
- 6. Torch should be perpendicular to workpiece.
- 7. Work cable should be attached as close to workpiece cut as possible.
- **8.** If you can see the arc coming through the bottom of the cut metal, it will eliminate guessing if your travel speed is correct.